


RENEILOE SEODIGENG



SANITI







In-SANITI




Flushing with clean water



Depleting limited water resources







In-SANITI



Fills up in 5 – 10 years



Unhygienic



Not considered dignified




Unsafe




VAPOORISE®: Is it a marriage between two toilets?









VAPOORISE®: Drying










VAPOORISE®: Thermochemical Treatment





SANITI

